

APPENDIX D

Hydrographs for Piezometers at Habitat Monitoring Sites




Figure D1. Hydrograph for piezometer at Blankenship Bend.




Figure D2. Hydrograph for piezometer at Havasu NE.




Figure D3. Hydrograph for piezometer at Ehrenberg.




Figure D4. Hydrograph for piezometer at Three Fingers Lake.




Figure D5. Hydrograph for piezometer at Cibola Lake.




Figure D6. Hydrograph for piezometer at Walker Lake.




Figure D7. Hydrograph for piezometer at Paradise.




Figure D8. Hydrograph for piezometer at Hoge Ranch.




Figure D9. Hydrograph for piezometer at Rattlesnake.




Figure D10. Hydrograph for piezometer at Clear Lake.




Figure D11. Hydrograph for piezometer at Ferguson Lake.




Figure D12. Hydrograph for piezometer at Ferguson Wash.




Figure D13. Hydrograph for piezometer at Great Blue Heron.




Figure D14. Hydrograph for piezometer at Mittry West.




Figure D15. Hydrograph for piezometer at Gila Confluence North.